Attorney Docket No.: 594728805US

Attorney Docket No.: 594728805US

Attorney Docket No.: 594728805US

Attorney Docket No.: 594728805US

Place Docket No.: 594728805US

Attorney Docket No.: 594728805US

By:

Douglas A. Gow

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: OOK KIM et al.

6.717.478

PATENT No.:

ISSUED:

APRIL 6, 2004

FOR: MULTI-PHASE VOLTAGE CONTROLLED

OSCILLATOR (VCO) WITH COMMON

MODE CONTROL

EXAMINER: JOSEPH CHANG

ART UNIT: 2817

CONF. No.: 1523

Request for Certificate of Correction under 37 C.F.R. §1.322 or §1.323

Certificate

MAY 1 4 2004 of Correction

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

- 1. The applicant(s) requests a Certificate of Correction to correct errors in the above-identified patent, which are listed on the enclosed Form PTO/SB/44.
- 2. Any errors on the part of the applicant are of a clerical or typographical nature or are otherwise minor in character. None of the requested corrections would constitute new matter or require reexamination of the patent.
- 3. Source of Error(s) and Payment of Fee:
 - All of the errors listed on Form PTO/SB/44 are believed to be due to mistake on the part of the USPTO (37 C.F.R. §1.322). Accordingly, no fees are believed to be due.
 - At least one of the errors occurred due to applicant's mistake made in good faith (37 C.F.R. §1.323).
 - A check covering the fee under 37 C.F.R. §1.20(a) (\$100.00) is enclosed herewith.

MAY 1 4 2004

- Please charge the fee under 37 C.F.R. §1.20(a) to Deposit Account No. 50-0665. This paper is provided in triplicate.
- Please charge any underpayment necessary for consideration of this paper to Deposit Account No. 50-0665.
- 4. Please send the Certificate of Correction to the undersigned at the address shown below.

Date: 5/4/04

Christopher J. Daley-Warkins Registration No. 34,807

Respectfully submitted,

Perkins Coie LLP

Correspondence Address:

Customer No. 25096 Perkins Coie LLP P.O. Box 1247 Seattle, Washington 98111-1247 (206) 359-8000 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

CERTIFICATE OF CORRECTION

PATENT NO: 6,717,478

DATED: April 6, 2004

INVENTOR(S): Ook Kim et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2

Line 51, insert period between "details" and "In";

MAILING ADDRESS OF SENDER:

Perkins Coie LLP PATENT-SEA PO Box 1247 Seattle, WA 98111-1247 PATENT NO. 6,717,478

No. of additional copies

=>

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, Washington, DC 20231.